

JAN 29 1982

DPM 2988 + - 1
Accelerator



OXY METAL INDUSTRIES CORPORATION

32100 STEPHENSON HWY., MADISON HEIGHTS, MICHIGAN 48071 (313) 583-9300

August 17, 1977

Douglas Aircraft Company
3855 Lakewood Boulevard
Long Beach, CA 90846

Attention: Mr. M. J. Veneroso

Dear Mr. Veneroso:

Your letter of May 23, 1977, addressed to our Buena Park facility was forwarded to the writer. Unfortunately, it arrived while I was out due to illness and has been buried with other work awaiting the time that I could catch up with it.

The questions concerning Oxyvate 301 B-30 will be handled by Mr. Winkler of the Udyllite Division.

The remaining items are not listed by the DOT in section 172101 CFR-49 and do not meet the definitions for hazardous materials.

None of these items have a flash point.

The items referred to are:

Accelerator, 170
Accelerator, 171
Neutralizer, 270
Parco® Cleaner 342

Neutralizer 201
Parcolene® Neutralizer 21
Bonderlube® 239

DPM 2988
DPM 2988-1
DPM 2989
DPM 2990

ATA 2208

DPM 3176

DPM 3176-1

DPM 5492

Douglas Aircraft Company
Page 2

August 17, 1977

There is one peculiarity in the above products, and that has to do with Accelerator, 170. This product is sodium bifluoride. This product is not rated as a hazardous product by DOT for shipment within this country either by surface or by truck, however, the IATA does list it as a Poison B with an IATA number 2208.

If there are any further questions, please contact the writer.

Yours truly,

PARKER DIVISION
OXY METAL INDUSTRIES CORPORATION



W. R. Cavanagh, Manager
Technical Services

WRC:so